Stückliste zum Schaltbild 561/I SABA 351 GW

Nr.	Widerstände	Bestell-Nr.	Nr.	Kondensatoren	Bestell-Nr.
17			37	5 000 pF	442/33
2	Ma. 50 K Ohm	181/26	38	5 000 ',,	442/33
3	Dr. 300 ,,	382/V	39	5 000 ,,	442/33
4	Dr. 100 ,,	382/XV	40	5 000 "	442/33
5	Dr. 6000 ,,	383/XII	41	10 ,,	462/3
6	Ma. 5 K ,,	213/29	42	0,1 μF	449/77
7	Ma. Potentiom. 10 K ,,	560/51	43	0,1 ,, }	442/77
8	Dr. 600 ,,	382/IX	44	500 pF	442/57
9	Dr. 100 "	382/XV	45	5 200 ,,	442/33
10	Ma. 1 M ,,	112/68	46	10 "	462/3
11	Ma. 1 M ,,	112/68	47	0,1 μF 🚶	442/77
12	Ma. 1 M ,,	112/68	48	0,1 ,,	442///
13	Ma. 0,3 M ,,	213/30	49	5 200 pF	442/33
14	Ma. 0,3 M ,,	213/30	50	50 ,,	462/11
15	Dr. 3000 ,,	383/X	51	15 ,,	462/4
16	Ma. Potentiom. 1,5 M ,,	560/52	52	0,1 μF	442/71
17	Ma. 0,1 M ,,	138/28	53	100 pF	462/12
18	Ma. 0,1 M ,,	138/28	54	5 000 ,,	442/33
19	Ma. 0,1 M ,,	138/28	55	8 μF	452/3
20	Ma. 50 K ,,	181/26	56	3 000 pF	442/53
21	Ma. 1 M ,,	112/68	57	1 000 ,,	442/58
22	Ma. 1K ,,	360/98	58	5 000 ,,	442/33
23	Dr. 150 ,,	382/XIV	59	5 000 ,,	442/33
24	Spannungsteiler 75/125 Ω	433/XI	60	0,5 μF	442/75
25	" " 100/350 Ω	433/XII	61	0,1 ,,	442/52
26	Dr. 2000 Ohm	383/XIX	62	2 000 pF	442/59
27	Dr. 6000 "	383/XII	63	25 μF	452/6
28	Dr. 2000 ,,	383/XIX	64	0,1 ,,	442/72
29	Dr. 2000 ,,	383/XIX	65	2 ,,	561/82α
30	Dr. 100 ,,	383/XXIV	66	32 "	430/70
31	Dr. 50 ,,	382/11	67	32 ,,	430/70
32	Dr. 9000 "	383/XIII			
33	Dr. 4000 ,,	383/XI			
34	Ma. 10 K ,,	138/30	1	Verschiedenes:	
			72	Siebdrossel	522/III
		1	73	Siebarossel	455/VII
		ì	74	Sicherung 0,35 Amp.	563/74
			75	Sicherung 0,35 Amp.	563/74
	Ì	1	76	Soffittenlampe 5 V 0,2 A	451/139
			77	Soffittenlampe 5 V 0,2 A	451/139
	Į	i	78	Sicherung 120 mA	590/113
ì)	}	79	Urdox 8 Volt 0,2 Amp.	451/140
Ma. = Massewiderstand Dr. = Drahtwiderstand					